

PUBLIC WORKSHEET DEPARTMENT

OR ILDINGS AND ROADS)

Oro Executive Engineer, Provincial Division No. 2, Robins -124001 Tel. 01262-251879

Tel-01262-251879 Fax-01262-251879

E. mail: - pwd-cepd2-rohtaka/hry.ulc.in

Memo no.: 13417

Dated: 24 12 24

The John Weley Convent School, Gohana Road, Rohtak

Subject:- Regarding building safety certificate for school building of John Wesley Convent School, Gohana Road, Rohtak.

Ref: - Your office letter dated 28.11.2020.

building of <u>John Wesley Convent School</u>, <u>Gohana Road</u>, <u>Rohtak</u> has been visually inspected by the SDE with concerned JE & reported that the above school building is safe for running the school. The above said building is not constructed in presence/ supervision of this department. Therefore, this office is not responsible in regard to structural stability of the school. As per general practice of the department. The department does not take any responsibility for seismic safety.

The general condition of the school building seems to be safe as per visual inspection for one year upto 24.12.2021.

D.A./Nil

Principal
John Wastey Convent
No 530616
C!
Gunsha Hoad, Rontok-123091

Executive Engineer, Provincial Division No.II, PW (B&R) Department, Rohtak

H 2021 - 5:00

1092